2006-05-31 Integration Scheduling Meeting

Wednesday, May 31, 2006 8:58 AM

	_							
•		Chief Summary:						
		• Tev access						
	 F4 wet engine connecting rod replaced 							
	 Secured CDF/D0 							
	0	First time low betas exercised.						
	 SY sequencer tested 							
	 BRF 19 had problems. 							
•	Notes from Integration:							
	 Access day 							
	 Longest job P3 line magnet replacement. 							
	0	Work in Yev until opini						
	0	Survey resources will be tight.						
	0	 Run Tevatron tomorrow. 						
	0	Need signoffs for Tev and NuMI.						
	0	Pace of accesses will slow down now						
•	Machi	chine Summaries:						
	0	Linac						
		Summary:						
		□ Statoins 1 and 5 fixed						
		$\ \square$ NTF today and tomorrow.						
		Requests:						
	0	Booster						
		• Summary:						
		 Matching 400 MeV to Booster 						
		□ Access						
		Replace vertical IPM - couple hours if don't have to break						
		vacuum.						
		◆ Pinger◆ RF work						
		• Q800 water leak.						
		Requests:						
	- Requests.							
	0							
		Summary:						
		□ 1 batch 3e12 beam - have tuning to do.						
		 Looked at NuMI extraction positions. 						
		□ Need to look at 150GeV orbits.						
	Requests:							
	0	Pbar						
		Summary:						
		 Yesterday - amplification was added to Prototype tanks. 						
		 Still can't see signals. 						
		 Accumulator trim supply regulator changed out 						
		 Debuncher trim chnaged out. 						
		□ Kicker remote control						
		 Damper noise source repaired. 						
		 No signal upstairs from Debuncher longitudinal schottky pickup. 						
		 Accumulator admittance measurments 						
		 Horizontal looks good, vertical not bad. 						

	 Debuncher bend field. Access - driven by prototype tank work Requests:
_	Tourstron
0	Tevatron • Summary:
	 Had Power Supplies on and conditioned separators. SY sequencer was the only machine to certify their sequences None of correctors or HOPS didn't ramp. Access ◆ B11 separator work
	 E11 vertical flying wire.
	■ Requests:
0	Recycler
	Summary:
	 Access today for flying wire work.
	 Ecool made electron beam.
	 Pelletron failure - have to a access - couple days time
	Requests:
0	SY120
	• Summary:
	□ Access
	Requests:
0	MiniBooNE
	• Summary:
	□ 1Ds in TLG
	Requests:
0	NuMI
	• Summary:
	☐ Finished electrical work
	□ Changed cores
	 Did PS testing last night.
	 Need a couple more wire pulls. Munter (Dehumidifier) system
	 Supervised access today -
	 Beam tomorrow.
0	CDF
Ŭ	• Summary:
	□ Closed plug yesterday
	 One power supply that failed and will be replaced today.
	 Gas flow problem for one muon system
	 Close up rest of detector at 4pm.
	Will need a secure at that time.
	Requests:
0	D0
0	Summary:
	Summary:Removed scaffolding in hall
	□ Replaced N muon shielding
	□ Detector surveys
	□ Finished Sup. Access - then S&S
	 Ramped magnets to nominal operating currents
	□ Back in Sup Access today
	Surveyers for four hours.
	 FPD wants to walk through to look at their equipment.

				FPD wants to walk through to look at their equipment. Search and secure 6pm.
		Dogu	ostor	No progress on muon counter.
		Requ	esis:	
	0	Cryo		
	Ü	Cryo	Summ	125/
		_	Juilli	F4 at 20K for P3 line work
			_	Will cool down with Linux consoles
				A4 HTS leads look normal.
			П	CHL have a transrex LCW leak.
			П	Once per day reboot MicroP
			П	office per day repose fileror
	■ Reque		_	sts:
			ricque	3.3.
	0	Mech	anical	
		•	Summ	narv.
				iai y i
			Reque	sts:
	0	ESH	_	
		•	SY120	for Meson, Mtest, F manholes
•	The P	lan	0.120	Tot Treson, Tresse, Timamiores
		Summ	, .	

o Requests: